LESSONS LEARNT: EMPTY CONTAINER DISLODGEMENT

LOCATION: CLYDEPORT - DUBLIN CONTAINERS & TRANSPORT LTD (DCATS)

WHEN: 21/01/2024



Event Description

On the evening of Sunday the 21st of January 2024, Storm Isha passed through the Dublin area, bringing with it an Orange Weather Warning and extreme high-speed gusts of wind. At 18:57, an empty 45ft container stacked near the perimeter fence of DCATS was blown from its position, toppling down the tiers of the stack and landing partially on the fence below (See Image 1 and 2).

A second 45ft container followed, toppling down the stack – this landed on the container located on the fence, which due to its angle acted like a fulcrum, allowing the second container to clear the fence and come to rest on the public roadway outside of the Terminal. Afterwards, a further stack of containers toppled within the confines of the Terminal – Two of these containers cleared the internal fence and came to rest on the Terminal Exit Lane.

No personal harm resulted – Damage was sustained to the DCATS perimeter fence, as well as a local authority lamp post.

Immediate/Direct Cause

Severe gale force wind speeds of over 120 km/h impacted the stacking area, resulting in empty containers toppling within the west end of DCATS.

Basic / Contributory Factors

- The containers were stacked no more than 'one high / 6 metres from the boundary', as per the associated Container Stacking Guidelines for the area.
- The sequence and position in which the containers toppled led to the second container clearing the fence.
- Stacking immediately adjacent to boundaries is covered within the DCATS ECH training, however was not clearly referenced within the associated Risk Assessment or Safe System of Work.
- On review following the event, several stacked containers in DCATS were noted not to be fully aligned 'casting to casting'.

Key Lessons


- While the containers were stacked no more than 'one high / 6 metres from the boundary', as per the associated Container Stacking Guidelines, this separation proved to be inadequate due to the particular sequence and manner in which the containers toppled Separation distance has now been increased by 40% and perimeter tier stacking configuration switched to 1-1-2-3-4-5 (See Image 3). The Container Stacking Guidelines are under review as a result of the incident.
- A TBT has been developed to highlight and refresh the Container Stacking Guidelines to all staff
 who work in DCATS. The associated Risk Assessment / Safe System of Work has also been
 updated to specifically reference mandatory boundary stacking rules.
- A documented check by the DCATS Supervisor has been introduced to ensure compliance with boundary stacking rules, as well as confirming that stacked containers are bunched tightly together and fully aligned 'casting to casting'. This will be undertaken routinely, rather than just when adverse weather is forecast.

Photos/Images

Image 1







BRIEF BY: 12/04/2024 DISPLAY UNTIL: 30/04/2024